


The image displays architectural drawings for the restoration of the tower of the Church of Maria SS. della Visitazione in Enna. On the left, a vertical section view shows the internal structure of the tower, including a spiral staircase and various levels. On the right, an exterior elevation of the tower is shown, featuring a series of arched windows and a decorative cornice. The drawings are rendered in black lines on a white background.

DIOCESI DI PIAZZA ARMERINA
Parrocchia Maria SS. della Visitazione
Duomo di Enna



PROGETTO ESECUTIVO:

Lavori di restauro e manutenzione straordinaria
della Chiesa Madre "Maria SS. della Visitazione"
e locali annessi sito in Enna, P.zza Duomo.

Siracusa - Torre campanaria.

Progetto	
ELABORATI: — piante percorso intorno torre campanaria	
A: quota livello portico e navata B: quota livello local 1° livello e sopra navata lat. sx	
TAV: 14.A	DATA: 10.08.2015
SCALA: 1:100	AGGIORNAMENTO
PROGETTISTA	COLLABORATORE

STUDIO DI PROGETTAZIONE AUGELLO & FONTANAZZA ARCHITETTI ASSOCIATI
Via M. Grimaldi, 8/b - Enna - tel/fax 0935/502310